





The summary drawing of air leakage from the main exhaust duct, Unit 4, Fukushima Daini Nuclear Power Station

June 8, 2011
 Tokyo Electric Power Company
 Fukushima Daini Nuclear Power Station



Air leakage at the welding with supporting legs, main exhaust duct, Unit 4
 (Confirmed on June 7, 2011)



magnify

